

Approved For Release 2002/06/10 : CIA-RDP69B00404R000100200005-8

DATE

S E C R E T

TO : ROUTING

FROM : CHIEF
ACTION: OXCART
INFO: PENDINGECID: 70355
T.H.

TO : FILE

S E C R E T 270653Z CITE

OXCART MAT

REF

1. IT APPEARS THAT THE RAIN REMOVAL SOLUTION WAS CONTAMINATED OR THERE WAS INSUFFICIENT RAIN TO MAKE IT REACT PROPERLY.
2. WE CHECKED THE SYSTEM ON THE GROUND AND FOUND THAT IT WAS SLOW TO CLEAR. WE DRAINED AND PURGED THE SYSTEM AND REFILLED. IT THEN WORKED NORMALLY WHICH POINTS TO POSSIBLE CONTAMINATION. THERE IS NO SHELF LIFE LIMITATION ON THE FLUID.
3. PROPER ACTION OF THE RAIN REMOVAL FLUID REQUIRES CONSIDERABLE RAIN. IT IS POSSIBLE THAT IN THIS CASE, AFTER BREAKING OUT UNDER THE CLOUDS, THERE WAS NOT ENOUGH RAIN FOR THE FAST ACTION DESIRED. THIS ASPECT WILL BE DISCUSSED WITH THE PILOTS.
4. THERE IS NO REAL PROBLEM AND NO ASSISTANCE IS REQUIRED.

S E C R E T

TOR: 270658Z OCT 67

S E C R E T

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

Approved For Release 2002/06/10 : CIA-RDP69B00404R000100200005-8